

Unit 3

Synchronous m/cs

[Syn Cr (or) Alternator
Syn m/o]

Alternator:-

DC generator
Stator \rightarrow field
Rotor \rightarrow Armature

Alternator
Armature
field

Adv of stationary armature.

- 1) Armature coils designed for 6.6kV or 11kV or 33kV coil insulation is easy if it is on stator.
- 2) the large ct can be easily collected from stationary armature. large ct collection thro' commutator and brush is very difficult.
- 3) Stationary armature construction leads to lesser leakage flux & hence reduced armature leakage reactance. This leads to improved voltage regulation.
- 4) Rotating field structure required only 2 slip rings so insulation reduced.
- 5) B'cos of low rge field coil on rotor the amount of Copper & insulation required are less. \therefore rotor has lesser weight & inertia.
- 6) Most of the heat is generated in armature. when armature is on stator, the ventilation & holes for cooling can be wider leading to better ventilation & heat dissipation.

Construction:-① Stator frame:-

- used for holding the armature stampings & coils in position.
- fabricated from mild steel plates welded together.

② Stator Core:-



* buildup of lamination of special magnetic iron or steel alloy. (dynamo sheet steel of 0.5mm thickness)

* Core is laminated to minimize loss due to eddy cts.

* lamination are stamped out in complete rings for smaller m/c or in segments for larger m/c.

* lamination are insulated from each other & have spaces b/w them for allowing the cooling air to pass through.

* different shapes of armature slots:-
 wide open semiclosed



③ Stator wdg:- Δ wdg Y wdg

arrangement of stator phase wdg in slots may be different types.

a) Concentrated wdg:-

No. of slots : No. of poles.

b) Distributed wdg:-

The conductors are embedded in several slots under one pole.


adv:- Distortion due to harmonics can be eliminated.

1) It reduces armature reaction & armature reactance.


2) Even distribution of Cu loss occurs & the cooling becomes efficient.

3) The conductors are evenly distributed.


c) Lap (single layer)



d) wave.



e) concentric or spiral wdg.



Pitch of the outer coil = 5; middle = 3; inner coil = 1

Rotor 2 types — Salient
Non salient or cylindrical.

1) Salient (or) projecting pole:-

* Used in low & medium speed alternation.

* It has large no. of projecting poles.

* Large diameter & short axial length.

* Poles & pole shoes are laminated to minimize heating due to eddy cts.

* Heavy magnetic wheel of Cast iron or steel of good magnetic quality.


b) Smooth cylindrical:-

* Used in very high speeds.

* 2 pole or 4 pole - Speed 3600 rpm (or) 1800 rpm.

* Small diameter & very long axial length.

* Rotor consists of a smooth solid forged steel cylinder, having a no. of slots milled out at intervals along the outer periphery for accommodating field coils.



Damping wdg:-

- * In addition to the dc field ^{salient} wdg, the Squirrel cage wdg is embedded in the pole faces of the alternator.
- * At normal cdn, the Squirrel cage wdg does not carry any ct since the rotor moves at synchronous speed.
- * If load changes, the rotor speed begins to fluctuate.
- * This produces momentary speed variation above & below the Synchronous speed (hunting).
- * A voltage is induced in the squirrel cage wdg.
- * ct flows in the wdg, reacts with the magnetic field of the stator.
- * the forces developed dampen the oscillation of the rotor.
- * This Squirrel cage wdg is called damper wdg.
- * It consists of heavy cu loads, they are short ckted at both ends by heavy cu rings.

frequency & Speed:

No. of cycles / revolution: No. of pairs of poles = $P/2$.

No. of revolution/sec = $N/60$.

No. of cycles/sec = $P/2 \times N/60 = PN/120$.

(or) f_{req} .

$$f = \frac{PN}{120}$$


$$N_s = \frac{120f}{P} \quad \text{--- syn speed}$$

Working principle:-

- * field magnets are magnetised by applying 125V or 250V through sliprings.
- * The rotor and field magnets are driven by the prime mover.
- * When the rotor rotates, the armature conductors are cut by the magnetic flux.
- * An emf is induced in the armature conductors.
- * Magnetic poles are alternately N + S pole, this emf acts in one direction and then in the other direction.
- * Hence an alternating emf is induced in the stator conductors.
- * direction of induced emf can be found by Flemings right hand rule.

Full-pitched coil - Coils having span which is equal to one pole-pitch (i) spanning one 180° .


Short pitched coil - Coil span is equal $5/6$ of a pole pitch.



Pitch factor (or) Coil span factor

k_p (or) $k_c = \frac{\text{Vector sum of the induced emfs/coil}}{\text{Arithmetic sum of the induced emfs/coil}} < \text{unity}$


In short pitch induced emf in the 2 sides of coil are not in phase hence their resultant given by vector is always $<$ their ar. sum



$$k_p = \frac{2E_s \cos \alpha/2}{2E_s}$$

$$\text{If } \alpha = 30^\circ \quad 5/6 \quad 180^\circ = 30^\circ$$

$$k_p = \cos 15^\circ = 0.966 \text{ always less than unity}$$



$\text{Slots/pole} = 180^\circ$
 $\text{cf slots} = 24 \text{ pole} = 4$
 $24/4 = 6 \leftarrow \text{full pitch}$

Distribution (or) Breadth (or) cog (or) Speed factor.


The ratio of
 The Vector sum of
 the emf induced in
 all the coils distributed
 in a no. of slots
 under one pole to
 the ar. sum of the
 coil side emf
 induced.

Let $\beta \rightarrow$ Angular displacement b/w the slots & its value is

m - No of slots/ph/pole

$\beta = \frac{180^\circ}{\text{No of slots/pole}} = \frac{180^\circ}{\frac{n}{2}}$

Emf induced in
1 phase under one
pole.



Resultant vge in
one polar group E_r

$A \cdot B = E_s = 2R \cdot \sin \beta/2$
 Emf induced in each coil side $= 2 \times \phi \cdot \sin \beta/2$

Arithmetic Sum $= m \cdot E_s = m \cdot 2R \cdot \sin(\beta/2)$

Vector Sum $= AE = E_r = 2R \cdot \sin(m\beta/2)$

$K_d = \frac{\text{Vector Sum}}{\text{Arithmetic Sum}} = \frac{2R \cdot \sin(m\beta/2)}{m \cdot 2R \cdot \sin(\beta/2)}$

The resultant
emf $E_r = 2 \times \phi \cdot \sin \frac{A \cdot O \cdot B}{2}$

$K_d = \frac{\sin(m\beta/2)}{m \cdot \sin(\beta/2)}$

each phase coils are not
 concentrated in one slot it
 is distributed in no. of
 slots to form polar group
 the emf generated in end
 connected are out of phase
 It has 36 slots 9 slots/pole
 If Baltham 1, 2, 3 belong to R
 phase it forms one polar
 group.

Cal. the distribution factor for 36 slot 4 pole, single layer 3φ cog.

$n = \text{No. of slots/pole} = 36/4 = 9$

$\beta = \frac{180^\circ}{n} = \frac{180^\circ}{9} = 20^\circ$

m : No. of slots/ph/pole.


$= \frac{36}{3 \times 4} = 3$

$K_d = \frac{\sin(m\beta/2)}{m \cdot \sin(\beta/2)} = 0.96$

Vector sum $E = E_s \cos 20^\circ$

$+ E_s + E_s \cos 20^\circ$
 $= 2E_s \cos 20^\circ + E_s$

$= 2E_s \times 0.9397 + E_s$
 $= 2.88E_s$



$K_d = \frac{\text{emf with distributed cog}}{\text{Emf induced if the Concentrated cog}} = \frac{3 \text{ slots/pole}}{15 \text{ slots/pole}} = \frac{E_r}{3E_s} = \frac{2.88E_s}{3E_s} = 0.96$

EMF eqn:

Z - No. of Conductors or coils/sides in series/ph.

$Z = 2T$ (T - No. of coils or turn per ph)

$P \rightarrow$ No. of poles.

$f \rightarrow$ freq of induced emf

$\Phi \rightarrow$ flux/pole in wb

k_d - distribution factor = $\frac{\sin(m\beta/2)}{m \cdot \sin(\beta/2)}$

k_c or $k_p = \cos(\alpha/2)$

k_f = form factor = 1.11

N - rotor speed (rpm)

In one revolution of the rotor ($60/N$) each stator conductor is cut by a flux of ΦP wbs.

$$d\Phi = \Phi P \quad dt = 60/N$$

$$\text{Avg emf induced/Conductor} = \frac{d\Phi}{dt} = \frac{\Phi P}{60/N}$$

$$N = 120f/P$$

$$\text{Av. emf/Conductor} = \frac{120f}{P} \cdot \frac{\Phi P}{60} = 2f\Phi$$

If there are Z conductors:

$$\text{Av. emf} = 2f\Phi \cdot Z = 4f\Phi T \quad (\because Z = 2T)$$

$$\text{Form factor} = \frac{\text{RMS Value}}{\text{Avg. Value}} = 1.11$$

$$\text{RMS Value of emf/ph} = 1.11 \cdot 4f\Phi T$$

\hookrightarrow actual value of induced emf if all the coils in a phase

coere 1) full pitched

2) Concentrated in one slot.

The actual available vge is reduced in the ratio of these 2 factors.

$$E_{mf}/p\phi = \frac{4}{\pi} k_d k_c \cdot f \phi T$$

If the alternator is star connected then the $V_L = \sqrt{3} V_{ph}$.

Alternator on load.

- * load is valid, its terminal vge is also found to vary.
- * This Variation in terminal vge V is due to the following reasons.



- 1) vge drop due to armature resistance, R_a .
- 2) Voltage " " leakage reactance, X_L .
- 3) " " " reaction.

a) Armature Resistance (R_a)

drop across R_a + inphase with I_a .

b) Armature leakage reactance (X_L)

When ct thro the armature conduction, fluxes are setup which donot comes the aingap, but the different paths such fluxes are known as leakage flux.



$$E = V + I(R_a + jX_L)$$

Armature Reaction:-

* the effect of armature flux on the main field flux:

* the p.f of the load has a considerable effect on the armature reaction.

3 Cases:-

- i) when load pf is UPF
- ii) " " Pf is zero lagging
- iii) " " " leading.

* mmf (or) Amp-turn wave.


* time relative to the poles its amplitude is proportional to the load ct but its position depends on the pf of the load.

DUPP:




- * the armature flux is unmagnetising.
- * the result is that the flux at the leading tips of the poles is reduced while it is fed at the tips.

2) Zero pf lagging:-



- * the armature flux is indirect opposition to the main flux.
- * the main flux is reduced.
- * demagnetizing - weakening of the main flux less emf is generated.

3) Zero pf leading:-



- * 90° forward
- * in phase with the main field flux.
- * results in added main flux.
- * the armature reaction is cordily magnetizing.
- * results in greater induced emf.

Synchronous Reactance:

For the same field excitation, terminal V_{ge} is decreased from its no. load value E_0 to V . b'coz of

- 1) drop due to armature resistance $I R_a$
- 2) drop due to leakage reactance $I X_L$
- 3) drop due to armature reaction $I X_a$.

$$X_s = X_L + X_a$$

$$\text{Total } V_{ge} \text{ drop } 2I R_a + j^2 I X_s^2 = I(R_a + j X_s)$$

Vector diagram:

E_0 - no load emf

E - loaded induced emf


V - terminal V_{ge}

I - armature ct/ph


$$Z = \sqrt{(R_a^2 + X_s^2)}$$

ϕ - load pf angle.


UPE



lagging pf.



leading pf




Voltage regulation:-

E_0 - No load emf

V - terminal vge - reduced under loaded cnd.

$$\% \text{ Reg} = \frac{E_0 - V}{V} \times 100$$



Determination of vge regulation.

1) Syn. Impedance (or) Emf method.

2) Ampere-turn or MMF method.

3) Zero pf method.

All these methods require i) R_a ii) OC iii) SC test.

Synchronous m/r:-

* operates at constant speed at no load to full load.

* Commutation is same as AC glr. It has a revolving field which must be separately excited from a DC source.

* pf can be varied over a wide range of lagging & leading values of changing the DC field excitation.


* high η & low initial cost.

* used to improve the pf of 3 ϕ AC endirectional ckt's.

Principle of operation:-

3-6

- * dc vge is applied to field wdg.
- * magnetic field produced by the resultant current flow will also be sinusoidally varying w.r to time.
- * 3 ϕ vge is applied to a 3- ϕ wdg the flux produced will be the resultant of all the 3 pulsating field.
- * 2 fictitious stator poles marked N_s + S_s assumed to rotate clockwise at a sync speed N_s .
- * Rotor poles (2) N_r + S_r are formed by the dc excitation.





- * N_s + N_r are together + S_s + S_r are together.
- * poles repel each other. N_s + S_s moving in clockwise direction.
- * N_r + S_r anticlockwise direction.
- * Half a cycle later, S_s N_r + N_s S_r attracted + the rotor tries to rotate in the clockwise direction.
- * that the rotor experiences torque in different directions every half a cycle.
- * this implies, directions every half a cycle.
- * As a result the rotor is at standstill due to large inertia.
- * It has no floating torque load cannot start by itself.
- * Rotor is rotated by a prime mover in the same direction as the synchronously rotating stator field.
- * N_s + S_r + N_r + S_s get attached + locked one another.
- * rotates at syn-speed.





Equivalent ckt of a synchronous m/s.

www.rejinpaul.com



Power developed by a syn. m/s:-

R_a is negligible as compared to its syn reactance X_s .



$$\cos \phi = \frac{AB}{I_a X_s}$$

$$AB = I_a X_s \cos \phi \quad (1)$$

$$\sin \alpha = \frac{AB}{E_b} \Rightarrow AB = E_b \sin \alpha \quad (2)$$

Equate (1) & (2)

$$E_b \sin \alpha = I_a X_s \cos \phi$$

$$KV; V \cdot E_b \sin \alpha = V I_a X_s \cos \phi$$

$$V I_a \cos \phi = \frac{E_b \cdot V}{X_s} \sin \alpha$$

↓
m/s power $W/P/Ph$

$$P_{in} = \frac{E_b V}{X_s} \sin \alpha = \frac{3 E_b V}{X_s} \sin \alpha$$

at loss - negligible so gross mechanical

Power $P_m = P_{in}$

$$P_m = \frac{3 E_b V}{X_s} \sin \alpha$$

Gross torque developed, $T = \frac{P_m}{N_m}$

$$T = \frac{3 E_b V}{\omega_m X_s} \sin \alpha$$

$$T = \frac{3 E_b V}{2\pi N X_s} \sin \alpha \quad \left(\omega_m = \frac{2\pi N}{60} \right)$$

$$= \frac{60}{2\pi} \frac{P_m}{N} \quad \boxed{T = \frac{9.55 P_m}{N} \text{ Nm}}$$

max pull out occurs when $\alpha = 90^\circ$

Diff torque of a syn. m/c.

1) Starting torque.

- * torque developed by the m/c when full vge is applied to its stator wdg.
- * Also called breakaway torque.
- * 10% in Centrifugal pumps.
- * 200 to 250% of full load torque in loaded reciprocating 2 cylinder compressors.

2) Running torque:-

- * torque developed by the m/c under running cnd.
- * determined by the horse power + speed of the driven m/c.
- * the peak horse power determines the max. torque that would be required by the driven m/c.
- * the motor must have a breakdown or max. running torque greater than this value in order to avoid stalling.

3) Pull in torque:-

- * Syn. m/c is started as IM till it run 2 to 5% below syn. speed.
- * then excitation is switched on + the motor pulls in to slip with the synchronously rotating stator field.
- * the amount of torque at which the m/c will pull in to step is called the pull in torque.

Pull out torque:-

- * the max torque which the m/c can develop without pulling out of step or synchronism is called pull out torque.

Starting methods:

From dc Source:


- * dc Compound mtr is Coupled to the shaft of the Syn mtr.
- * Syn mtr is excited & synchronized with the ac supply mains.
- * dc mtr is disconnected from the Supply Dampers cage (or) cage winding.
- * dampers cage is Connected on the rotor poles of the Syn mtr.
- * It Consists of short Circuited Co bars embedded in the face of the field poles.
- * 3 ϕ Supply is Connected to the Stator cage a rotating field is established.
- * This rotating field interacts with the dc produced in the rotor cage & produces a torque to start the mtr like 3 ϕ Ind.
- * After attain 95% of the Syn speed the rotor cage is Connected to exciter terminals & the rotor is finally magnetically locked by the rotating field of the stator & the mtr then runs at Syn. speed.

Direct Coupled IM

- * No of poles of the IM is kept 2 or less than the no of poles of the Syn mtr.
- * Syn Speed can be easily attained.
- * Before the Syn mtr is Connected to a supply it should be synchronized with the busbar.
- * Once the normal operation is made the small IM can be removed.

load + dampers:

- * while starting the dampers bars are not Connected to the end rings but are Connected to external resistances third slip rings.



→ When V_{ge} is applied, the rotor is stationary. The rotating field of the stator wdg induces a very large e.m.f in the rotor during the starting period. Though the value of this e.m.f goes on decreasing as the rotor gathers speed.

→ Normally field wdg is meant for 110V but during starting period there are many thousands of volts induced in them.

→ Rotor wdg has to be highly insulated for withstanding such V_{ges} .



→ When full line V_{ge} is switched on to the armature at rest, a very large current, usually 5 to 7 times the full load a.c. current is drawn by the motor.

Procedure for starting a syn. m/s.

1. First main field wdg is S.C
2. Reduced V_{ge} with the help of auto-transformer is applied across stator terminals. The m/s starts up.
3. When it reaches a steady speed, a weak d.c excitation is applied by removing the S.C on the main field wdg. If excitation is sufficient then the m/c will be pulled in to synchronism.
4. Full supply V_{ge} is applied across stator terminals by cutting out the auto-transformers.
5. The m/s may be operated at any desired power factor by changing the d.c excitation.

Construction of V Curves:-

- The V-Curves of a Syn m/s show how ar. current varies with its field current when m/s i/p is kept constant.
- These are obtained by plotting a.c. armature ct against d.c. field ct while m/s i/p is kept constant and are so called because of their shape.
- To draw this curve the m/s is run from constant voltage + constant frequency bus-bars.
- prior i/p to m/s is kept constant at a definite value.
- field ct is \uparrow ed in small steps + corresponding ar. currents are noted.
- when plotted we get a V-curve for a particular constant m/s i/p.
- Similar curves has to be drawn by keeping m/s i/p constant for different values.



- The ct taken by the m/s will be minimum when the ct I_a is inphase with the vge or the p.f of the m/s is unity.