


CORNER RECORD

BK 56 PG 35APN No. 84A - 0046 - 008 - 10 (Optional) Document Number CR-3404

CASTRO VALLEY-UNINCORPORATED

County of ALAMEDA, CaliforniaBrief Legal Description MONUMENTS TO REPLACE DESTROYED AND MISSING IRON BOLTS ON NORBRIDGE.

CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☐
Rancho ☐ Other ☒
Date of Survey MAY, 2001

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner - Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

In compliance with Section 8771 of the Professional Land Surveyors' Act, this corner record is being filed to ESTABLISH _____ / REESTABLISH ☒ the position of an existing monument PRIOR _____ / SUBSEQUENT ☒ to street or highway reconstruction. (Use this portion only when applicable.)


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: STANDARD COUNTY MONUMENTS WERE SET USING INFORMATION FROM CR-1148 & CR-1149. SEE DRAWING NEXT PAGE FOR DESCRIPTION OF MONUMENTS SET.

A description of the physical condition of the monument as found and as set or reset: TWO STANDARD COUNTY WELL MONUMENTS WITH NIPPLED BRONZE DISKS WERE SET TO REPLACE AN IRON BOLT AT THE INTERSECTION OF ASHFIELD AND NORBRIDGE AVENUES AND ALSO A MISSING IRON BOLT AT THE ANGLE POINT OF NORBRIDGE AVE., JUST WESTERLY OF WILBEAM AVE. SEE PAGE 2 FOR STAMPING.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 6/18/ 2008.

Signed Gregory Donald Hollfelder L.S. or R.C.E. Number 5918



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 6-18 2008 and examined and filed 11-17-2013.

Signed Frederick R. Penland, Jr. Title County Surveyor



County Surveyor's Comment _____

